## UNCLASSIFIED

AD 4 2 2 4 9 7

## DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION, ALEXANDRIA, VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

## Best Available Copy

TECHNICAL REPORT 3110



OF
INITIATING PB-RDX PELLETS
USING THE
M46 STAB DETONATOR

LEONARD SHAINHEIT ROBERT L. WAGNER

COPY NO. \_\_\_\_ OF \_\_\_\_

SEPTEMBER 1963

PICATINNY ARSENAL DOVER, NEW JERSEY

The findings in this report are not to be construed as an official Department of the Army Position.

## DISPOSITION

Destroy this report when it is no longer needed. Do not return.

## DDC AVAILABILITY NOTICE

Qualified requesters may obtain copies of this report from DDC.

## TECHNICAL REPORT 3110

DETERMINATION OF THE FEASIBILITY
OF
INITIATING PB-RDX PELLETS
USING
THE
M46 STAB DETONATOR

ВΥ

LEONARD SHAINHEIT ROBERT L. WAGNER

SEPTEMBER 1963

REVIEWED BY:

D. E. SEEGER

Chie#, Explosives

Initiator Section

APPROVED BY:

E. H. BUCHANAN Chief, Artillery

Ciner, Artificity

Ammunition Laboratory

AMMUNITION ENGINEERING DIRECTORATE
PICATINNY ARSENAL
DOVER, NEW JERSEY

## TABLE OF CONTENTS

Section		Page
I	INTRODUCTION	1
II	SUMMARY	2
III	CONCLUSION	3
IV	RECOMMENDATION	3
V	STUDY	4
	APPENDICES	
	A. Tables	7
	B. Figures	17
	ABSTRACT DATA	26
	TABLE OF DISTRIBUTION	27

#### SECTION I

#### INTRODUCTION

This investigation was conducted to determine if pellets of PB-RDX explosive could be initiated directly by the M46 Stab Detonator.

Usually PB-RDX, a relatively insensitive secondary explosive, is not used in applications where it is required to be initiated directly by a detonator. By employing the proper design techniques and utilizing a detonator which has sufficient output, a system for directly initiating PB-RDX pellets would be feasible.

Recently, a proposal was made for the development of a helicopter landing device utilizing certain existing hardware. Combining the fuze and main charge by simple logical means would create a system wherein the M46 Detonator would be required to initiate PB-RDX pellets directly. Prior to proceeding with the development, a program was initiated to determine the feasibility of using the M46 Detonator to initiate a PB-RDX pellet.

In the series of tests conducted, restrictions were imposed upon the system consisting of barriers (air gaps, stainless steel and brass strips), extreme cold temperature (-65°F), and reduced detonator confinement. The results of these tests are contained in this report.

#### SECTION II

#### SUMMARY

The M46 Stab Detonator was used to initiate PB-RDX pellets under varied test conditions.

Tests were conducted at ambient temperature with the M46 Detonator in direct contact with the PB-RDX pellet and with air gaps of up to 0.2 inch or barriers of up to 0.010 inch-thick stainless steel. There was no failure of the detonator to initiate the PB-RDX pellet in these tests. However, when an air gap of 0.4 inch or a barrier of 0.036 inch-thick brass was introduced into the system failures were produced in several instances.

Similar tests were conducted at ~65°F. In these tests, no failure of the detonator to initiate the pellet was observed when the detonator was in direct contact with the pellet. However, when an air gap of 0.2 inch was introduced between the detonator and pellet, failure was observed.

## SECTION III

#### CONCLUSION

It is feasible to directly initiate PB-RDX pellets using the M46 Stab Detonator.

#### SECTION IV

## RECOMMENDATIONS

- l. Work should be continued on the proposed helicopter landing device with the approach of using the M46 Stab Detonator to initiate PB-RDX pellets.
- 2. The final design should be subjected to an environmental and reliability test program.

#### SECTION V

#### STUDY

Tests were conducted to determine if the M46 Stab Detonator (Figure 1) could initiate a PB-RDX pellet (Figure 2) under a variety of conditions. The test results are summarized in Table 1.

Detailed results of the entire test series are recorded in Tables 1-10. These results are discussed further in the following.

A test group of 26 each M46 Stab Detonators were placed in direct contact with PB-RDX pellets (Figure 3a). In the test, the detonators were required to initiate the PB-RDX pellets directly. To prevent pitting within the dent made in steel plate by the detonation of the PB-RDX explosive, a thin film of vaseline petroleum jelly was placed between the pellet and plate as per MIL-STD-316. A description of the materials used is given in Appendix C. The detonators were fired by dropping a two-ounce steel ball from a height of 13 inches onto the firing pin. A steel dent test was used to determine output of the PB-RDX pellet. A Starret depth gauge with stand as per MIL-STD-316 was used to measure the dent formed in the steel plate. Values are recorded in Table 2. The average depth of indentation, as recorded in the table, is 0.058 inch. Based on experience this is considered indicative of a high order detonation. The results obtained were encouraging since no failure was encountered even though the confinement afforded the detonators by the polyethylene fixtures (Figure 4) was less than that planned for it in the end item, the M607 Mine fuze (Figure 5).

Using a set-up as in Figure 3a, ten each M46 Stab Detonators and PB-RDX pellets were tested at -65°F. The indentations made in steel plate are recorded in Table 3. As shown in the table, the average dent obtained was 0.042 inch. This value was considerably lower than the 0.058 inch obtained in the previous test. It was observed that the vaseline petroleum jelly located between the pellet and the steel plate had? ardened at ~65°F, thereby creating a barrier between the pellet and steel plate. This vaseline barrier attenuated the pellet output, producing the relatively small indentations. To determine the validity of this explanation, a control test was conducted in which the only change made was to omit the vaseline coating. The results are also reported in Table 3. The average dent produced was 0.053 inch. This dent is appreciably different from 0.042 inch obtained with the vaseline at -65°F and seems to confirm the above reasoning. The results show that the M46 Detonator is capable of effecting initiation of PB-RDX when subjected to extreme cold temperature. It should be noted that the detonator confinement used in this test, as in the previous test, was only a thin polyethylene sleeve.

To create a more difficult task for the detonators, they were separated from the pellets by air gaps of  $0.200 \pm 0.009$  inch (except in two cases, i.e., 0,273 and 0,313 inch). The loaded fixture (Figure 3b) was tested in the apparatus shown in Figure 3a. The detonators were held in place by an epoxy adhesive, Hysol 2038 using Hardner C, No. 3475, described in Appendix C. Before conducting these tests, an investigation was conducted to ascertain if the adhesive had sufficient strength to hold the detonator in position. This was necessary to assure that the detonator was not pushed down on top of the pellet (thereby reducing the size of or eliminating the air gaps completely) when the stab pin was struck by the ball. Five plugs (cut from 1/4-inch aluminum rod to the size of the M46 Detonator) were substituted for the detonators and placed in the apparatus in Figure 3b. Measurements of air gaps before and after ball drop were made and are recorded in Table 4. A comparison of the average air gap before and after ball drop indicated that the epoxy adhesive had sufficient strength to reliably hold the detonator in place.

In the 0.2-inch air gap test at ambient temperature, the indentations made in steel plate by the PB-RDX pellets are recorded in Table 5. A comparison of the average indentation produced with the detonator directly on the pellet (0.058 inch) and with the detonator separated by a 0.2-inch air gap (0.059-inch), showed there was no apparant change in pellet output due to imposition of this air gap.

However, in one of these tests the detonator was not initiated. There are several possible explanations accounting for this occurrence. First, it is possible that the steel ball used in the drop test did not strike the stab pin squarely, thereby transfering an insufficient quantity of impact energy to the detonator. A second explanation is based upon the contention that an excess of epoxy adhesive hardened above the detonator and had sufficient strength to prevent the stab pin from penetrating into the detonator. Examination of the detonator and test apparatus indicated that the former expanation was applicable. No adhesive was observed above the detonator but it was noticed that a bolt holding the steel pipe in which the steel ball was dropped (Figure 3a), had loosened. The pipe was tilted at an angle indicating the ball did not strike the stab pin squarely. The bolt was tightened and the pipe realigned. The set-up was examined before each successive test to prevent any future recurrence.

The test was repeated at -65°F using an air gap of about 0.2 inch between the detonator and pellet. The results of this test are recorded in Table 6. The average depth of indentation in steel plate was 0.052 inch. This value agrees with that obtained in the control test conducted at -65°F with no air gap imposed between the detonator and pellet. Just as in the

control test, vaseline was not used between the pellet and steel plate. Thus, the result obtained, further substantiated the opinion that at a cold temperature the vaseline hardened forming an attenuating barrier between the pellet and steel plate.

In the next test, the pellets were separated still farther from the detonator by air gaps of 0.399 to 0.031 inch. In 11 of the 14 tests, the pellets were successfully initiated. The results are recorded in Table 7. It is considered that the failures are due to the presence of the relatively large air gaps employed in these tests. As the conditions imposed upon the system become more severe, the chance of failure increases. It is apparent from the results that 0.319-inch air gap far exceeds the air gap over which PB-RDX can be reliably initiated by the M46 Detonator.

Figure 3c shows the loaded fixture for determining the affect of metal barriers on the probability of initiating PB-RDX by the M46 Stab Detonator. The test results are recorded in Tables 8-10. The average indentations obtained in these tests ranged from 0.064 to 0.066 inch. The value obtained in the tests with the detonator in direct contact with the pellet, was 0.055 inch.

The increased average dent was attributed to the presence of the metal barrier between the detonator and pellet. Several theoretical explanations accounting for this phenomenon are available. However, determining the validity of these would necessitate further investigative effort which the authors believe is beyond the scope of this task.

As seen from the tables, only the 0.036 inch-thick brass strip (in 3 out of 10 tests) attenuated the detonator output sufficiently to prevent pellet initiation. These failures were not unusual since the barrier thickness was large. The output of the detonator was attenuated to a value which produced a detonation rate near the critical value for the explosive. Being in a critical region, failures were to be expected.

The tests described above were conducted over a wide range of rather severe conditions. This was necessary to determine not only the feasibility of initiating PB-RDX pellets using the M46 Detonator, but also to obtain some information concerning the limitations under which this could be effected. The findings of these tests indicated that there is a range of design conditions under which reliable functioning may be obtained. Since it is expected that the intended end item design will be within this range, it is suggested that work be initiated on application of an M46 Detonator PB-RDX system in the helicopter landing device.

APPENDICES

APPENDIX A

TABLES

TABLE I

SUMMARY OF TEST CONDUCTED TO DETERMINE THE FEASIBILITY OF INITIATING PB-RDX PELLETS USING THE M46 STAB DETONATOR

Range of Dent in Steel (Inches)	0.048 0.038 0.055 0.048 0.053 0.061
Range of I in Steel (Inches)	0.066 0.044 0.065 0.055 0.068 0.068
Avg. Dent in Steel (Inches)	0.058 0.042 <sup>2</sup> 0.059 0.056 0.064 0.064
Nr. PB-RDX Pellets Not Initiated	0 0 1 1 4 0 0 8
Nr. PB-RDX Pellets Initiated	26 10 11 10 11 10 7
Nr. Tested	26 10 12 11 14 10 10
Test Temp	A. T.1 -65 A. T65 A. T. A. T. A. T. A. T.
n Detonator Material	None None Air Air Air Stainless Steel Stainless Steel Steel Brass
Gap or Barrier Between Detonator and Pellet  Thickness; Inches  Material	0.200±0.0093 0.199±0.008 0.399-0.031 0.005 0.010

NOTES:

Ambient Temperature (approx. 70° F) 1.

The low value is attributed to a vaseline barrier between pellet and steel block (see pages 4-6 for further details).

Two air gaps were unintentionally made larger (0.273 and 0.313 inch). w 4

The M46 Stab Detonator was not initiated in this test.

TABLE II

## INITIATION OF PB-RDX PELLETS USING THE M46 STAB DETONATOR AT AMBIENT TEMPERATURE

Test Number	Depth of Indentation in Steel Plate
	(inches)
1	0.062
2	0.066
3	. 0.058
4	0.065
5	0.062
6	0.061
7	0.055
8	0.057
9	0.051
10	0.058
11	0.058
12	0.062
13	0.060
14	0.059
15	0.059
16	0.059
17	0.060
18	0.059
19	0.055
20	0.060
21	0.057
22	0.056
23	0.053
24	0.057
25	0.048
26	0.052
Avg	0.058
Max	0.066
Min	0.048

Note: Test set up is shown in Figure 3a.

The detonator was initiated by a twoounce steel ball dropped 13 inches

TABLE III

INITIATION OF PB-RDX PELLETS BY THE M46 STAB DETONATOR
AT -65°F

Test Number	Depth of Indentation in Steel Plate (inches)	Control Test Number *	Depth of Indentation in Steel Plate (inches
1	0.040	1	0.055
2	0.044	2	0.054
3	0.038	3	0.056
4	0.040	4	0.053
5	0.041	5	0.055
6	0.043	6	0.054
7	0.042	7	0.056
8	0.038	8	0.049
9	0.042	9	0.051
10	0.042	10	0.050
Avg	0.042		0.053
Max	0.044		0.056
Min	0.038		0.049

Note: Test set up is shown in Figure 3a

\*No vaseline was used to hold pellet on steel plate.

The detonator was initiated by a two-ounce steel ball dropped 13 inches.

QUALITATIVE INDICATION OF EPOXY ADHESIVE 1 STRENGTH

UNDER IMPACT 2

Number Tested		Air Gap Before Impact (inches)		ir Gap After mpact (inches)
1		0,207		0.207
2		0.199		0.199
3		0.202		0.201
4		0.209		0.210
5		0,204		0.204
	Avg	0.204	Avg	0.204

Note: Test set-up shown in Figure 3b.

Aluminum rods, equal dimentionally to the M46 Stab

Detonator, were used in place of the detonators.

PB-RDX pellets were not used in this test.

- 1. Hysol epoxy adhesive, No. 2038, using Hardener C, No. 3475.
- 2. A two-ounce steel ball was dropped 13 inches onto the stab pin.

TABLE V

## INITIATION OF PB-RDX PELLETS USING THE M46 STAB DETONATOR ACROSS AIR GAPS AT 70°F

Test Number	Air Gap (inches)	Depth of Indentation in Steel Plate (inches)
1	0.206	0.061
2	0.203	0.057
3	0.207	0.058
4	0.208	0.055
5.	0.199	0.065
6	0.206	0.059
7	0.209	0.061
8	0.273	0.058
9	0.202	0.061
10	0.206	0.058
11	0.313	0.061
12	0.209	*
Avg	0.219	0.059
Max	0.313	0.065
Min	0.199	0.055

Note: The test set up is shown in Figure 3b.

\*The M46 Stab Detonator did not fire.

The detonator was initiated by a two-ounce steel ball

dropped 13 inches.

TABLE VI

INITIATION OF PB-RDX PELLETS USING THE M46 STAB DETONATOR
THROUGH AIR GAPS AT -65°F

Test Number	Air Gap (inches	Depth of Indentation in Steel Plate (inches)
. 1	0.201	0.051
2	0.205	0.048
3	0.199	*
4	0.203	0.053
5	0.207	0.050
6	0.201	0.048
7	0.706	0.054
8	0.205	0.051
9	0.207	0.053
10	0.204	0.055
11	0,205	0.054
Avg	0,204	0.052
Max	0.207	0.055
Min	0.048	0.048

Note: The test set up is shown in Figure 3b.

\*The PB-RDX pellet failed to detonate.

The detonators were initiated by a twoounce steel ball dropped 13 inches.

TABLE VII

INITIATION OF PB-RDX PELLETS USING THE M46 STAB DETONATOR
THROUGH AIR GAPS AT 70°F

Test Number	Air Gap (inches)	Depth of Indentation in Steel Plate (inches)
1	0.380	0.058
2	0.392	0.053
3	0.391	0.055
4	0.389	*
5	0.395	0.057
6	0.371	0.059
7	0.399	*
- 8	0.377	0.053
9	0.383	*
10	0.370	0.053
11	0.369	0.059
12	0.368	0.060
13	0.394	0.057
14	0.399	0.059
Avg	0.384	0.056
Max	0.399	0.060
Min	0.368	0.053

Note: The test set up is shown in Figure 3b.

\*The PB-RDX pellets failed to detonate.

The detonators were initiated by a two-ounce steel ball dropped 13 inches.

TABLE VIII

## INITIATION OF PB-RDX PELLETS USING THE M46 STAB DETONATOR THROUGH A 0.005 INCH-THICK STAINLESS STEEL BARRIER AT 70°F

Test Number	Depth of Indentation in Steel Plate (inches)
Test Number	bteel I late (menes)
1	0.068
2	0.061
3	0.067
4	0.063
5	0.064
6	0.064
7	0.064
8	0.061
9	0.066
10	0.061
Avg	0.064
Max	0.068
Min	0.061

Note: Test set up is shown in Figure 3c.

The detonators were initiated by a twoounce steel ball dropped 13 inches.

TABLE IX

## INITIATION OF PB-RDX PELLETS BY THE M46 STAB DETONATOR THROUGH A 0.010 INCH-THICK STAINLESS STEEL BARRIER AT 70°F

Test Number	Depth of Indentation in Steel Plate (inches)
1	0.063
2	0.063
3	0.060
4	0.067
5	0.068
6	0.065
7	0.065
8	0.055
9	0.065
10	0.068
Avg	0.064
Max	0.068
Min	0.060

Note: Test set up is shown in Figure 3c.

The detonators were initiated by a twoounce steel ball dropped 13 inches.

TABLE X


## INITIATION OF PB-RDX PELLETS BY THE M46 STAB DETONATOR THROUGH A 0.036 INCH BRASS BARRIER AT 70°F

Test Number	Depth of Indentation in Steel Plate (inches)
1	0.064
2	0.065
3	*
4	0.065
5	0.065
6	0.059
7	*
8	*
9	0.070
10	0.072
Avg	0.066
Max	0.072
Min	0.059

Note: Test set up is shown in Figure 3c. \*PB-RDX pellets failed to detonate. The detonators were initiated by a twoounce steel ball dropped 13 inches.


APPENDIX B

**FIGURES** 



NOTE:
FURTHER INFORMATION MAY BE OBTAINED IN
ORDNANCE CORPS DRAWING NO. 8797793.

## DETONATOR, STAB, M46



NOTE :


WEIGHT :- 3.04 - .14 GRAMS

MATERIAL :- POWDER, PBX, TYPE A,

.057 LB/CU.IN.


FOR FURTHER INFORMATION SEE ORDNANCE CORPS DING NO. XP-1/3/88.

## PB-RDX PELLET




TEST SETUP SHOWING DETONATOR DIRECTLY ON PELLET

FIGURE 3a.




TEST SETUP SHOWING DETONATOR SEPARATED FROM PELLET BY AIR GAP

FIGURE 36.





TEST SETUP SHOWING DETONATOR SEPARATED FROM PELLET BY METAL BARRIER.



HOLDER, FIRING PIN MOLDED POLYSTYRENE, TYPE I, SPEC L-P-416

NOTES:1-FLASH MARKS AND DRAFT ALLOWABLE ONLY
ON EXTERNAL SURFACE.
2-SPEC MIL-A-2550 APPLIES.





SPEC MIL-A-2550 APPLIES.

FIGURE 6

## APPENDIX C DESCRIPTION OF MATERIALS

## DESCRIPTION OF MATERIALS

1. M46 Stab Detonator - Drawing No. 8797793 in Figure 1.

2. PB-RDX Pellets - Drawing No. XP113188 in Figure 2.

3. Polyethylene Fixture - Drawing in Figure 4.

Rockwell Hardness

4. Stab Pin - Drawing in Figure 6.

5. Steel Plate:

Length	1.0 inch
Width	1.0 inch
Height	0.5 inch
Specification	QQ-S-635
Type Steel	FF1020

6. Steel Ball:

Weight	2 ounces
Diameter	0.9 inch
Height above Stab Pin	13 inches

7. Hysol 2038 Epoxy Adhesive Using Hardener C, No. 3475:

Manufactured by - Hysol Corporation, Olean, New York

B70-B95

Tensile-Shear Strength for aluminum to aluminum bonding after cure at  $70^{\circ}$  F  $- \cdot 1,820$  psi

ABSTRACT DATA

#### **ABS TRACT**

Accession No. AD

Picatinny Arsenal, Dover, New Jersey

DETERMINATION OF THE FEASIBILITY OF INITIATING PB-RDX PELLETS USING THE M46 STAB DETONATOR

Leonard Shainheit Robert L. Wagner

Technical Report 3110, September 1963, 28pp, figures, tables, Unclassified report from the Artillery Ammunition Laboratory, Ammunition Engineering Directorate.

The M46 Stab Detonator was used to initiate PB-RDX pellets under varied test conditions.

Tests were conducted at ambient temperature with the M46 Detonator in direct contact with the PB-RDX pellet and with air gaps of up to 0.2 inch or barriers of up to 0.010 inch-thick stainless steel. There was no failure of the detonator to initiate the PB-RDX pellet in these tests. However, when an air gap of 0.4 inch or a barrier of 0.036 inch-thick brass was introduced into the system failures were produced in several instances.

Similar tests were conducted at -65°F. In these tests, no failure of the detonator to initiate the pellet was observed when the detonator was in direct contact with the pellet. However, when an air gap of 0.2 inch was introduced between the detonator and pellet, failure was observed.

#### **UNCLASSIFIED**

- 1. Explosives Materials -Initiation
- 2. Electric detonators
- I. Shainheit, Leonard
- II. Wagner, RobertL.
- III. PB-RDX pellets
- IV. M46 stab detonator

#### UNITERMS

Initiation
Explosive
Pellets
Detonator
Stab
M46
Shainheit, L.
Wagner, R. L.

TABLE OF DISTRIBUTION

Secretaria Zo

Tarrey November of New Jersey

AD.

THE TERMIN THOS OF THE FEASIBILITY OF INITIA-NO PRINT PLUEDS USING THE MASSTAB DET-80111

Bulletin States

Control of the Section of the Arithmetical Section Sec

12. THE SCALL FOR A CONTROL OF THE REPX pol11. the 3.18 a visite the PB-RDW pollet and Control of the Control

# UNCLASSIFIED

- 1. Explosives Materials - - Initiation
- 2. Electric Detenators
- H. Wagner, Robert L. I. Shainheil, Lampied
- IV. M46 stab detonator III, PB-RDX pellets

## CNITERMS

: 111121,3711011 Explosive 510 100

D. tonator 5431 50

11.7 C.F.

# UNCL ASSIFIED

1. Uxplosives Materials

Shanked Leaned

H. Wagner, Robert L.

SINHTHITCH

11.1.1.1.1.1.1

And the state of t

The May be desired as a second of the second

Frobotis.  N146

Devices a meroscoper will the FB KON pellet and

Accession No.

Picatinny Arsenal, Dover, New Jersey

7

DETERMINATION OF THE FEASIBILITY OF INITIA-ING PB-RDX PELLETS USING THE M46 STAB DET-

Leondard Shambert

ONATOR

Robert 1. Wagner

Fedinical Report 3110, September 1963, 28 pp. figures. tables. Unclassified report from the Artill, ry Ammunition Laboratory, Aramunition Engineering Directorate,

The Ma6 Stab Defonator was used to initiate PB-RDN pellets under varied test conditions,

Detonator in direct contact with the PB RDX pellet and lests were conducted at ambient temperature with the M46

(10 VO)

# LNCLASSIFIED

---

J. Ply triv. Detonatory - Inthation

DE LEMINATION OF THE LEASHED TO OF INTER-THAT THE SHILL SHOW THE RESTREET

The State of the s

#011 V.)

A Area L David New Prev

Sec. 19 Au

19 PR NDV pellets
19 Min with detector

Detentator 51.15 648. The property of the first operation operation of the first operation operation operation operation operation operation operation ope UNCLASSIFIED

Parting Argend, Dover, New Jersey Accession No.

AD

DETERMINATION OF THE FEASIBILITY OF INITIA-ING TH-RDY PULLETS USING THE M46 STAR PLT. CNATOR

1 . ondard Shainhad

R. Jury ! Wagner

tables. Unclassified report from the Arallery Amont, ton To bin all Report 3110, September 1963, 28 pp. France Laboratory, Ammunition Engineering Directorate,

The M46 stab Defonator was used to outlate PB-RDN pelilets moler varied test conditions. lests were conducted at ambient temperature with the N46 Detonator in direct contact with the PB-RDX pellet and

## UNCLASSIFIED

1. Explosives Materials - - Initiation

2 Plactric Detectors IV. Mile stab Jeneman I. Shattilliteit, I com the H Wagner, Robert I III. PB RDN peller

STABLY.

Detenator "Applying industria P. Bet Stail

# CACH ASSIFIED

917

L. Espiestro, Nater CHURSSELED

P 1 - Starbett, I van. - - Brithatun

Wagner, I done M. The HDN 1444 W. Mr. Age 247

Determite · sample : 1116 言言になってい

(4.1.5.1)

				5.	1
0.010	det-	How-	inch-	Were	
with air gaps of up to 0.2 inch or barriers of up to 0.010	incluther k stainless steel. There was no failure of the det-	ondor to initiate the PB-RDX pellet in these tests. How-	ever, when an air gap of 0.4 inch or a barrier of 0.036 inch-	thuck brass was introduced into the system failures were	
uriers of	no failu	in these	barrier	system	,
or ba	W.28	ellet	or a	the	
inch	There	DX p	1 inch	l into	500
to 0.2	cel.	PB-R	of 0.	educe	product in several instances
dn J	7/10	e the	ir gal	intro	1020
th vd1	stain	nitiat	an a	W.AS	1.35
111 E.	<u> </u>	r to i	s hen	brass	73.0
with.	11 11	metos	VOT.	- Y	produ

no failure of the detonator to initiate the pellet was observed when the detonator was in direct contact with the pellet. However, when an air gap of 0.2 inch was intro-duced between the detonator and pellet, failure was ob-In these tests, Sundar tests were conducted at -65 F. served.

## UNCLASSIFIED UNITERMS

Wagner, R. L. nainheit. L.

# **UNCLASSIFIED**

# UNCLASSIFIED

or gaps of up to 0,2 inch or barriers of up to 0,010

near think stunless steel. There was no failure of the detector to murite the PB-RDX pellet in these tests. How-

413 bros was introduced into the system failures were

over when an air gap of 0.4 inch or a barrier of 0,036 inch

Wagner, R. I., Shainheit, 1..

UNITERMS

UNCLASSIFIED

with air gaps of up to 0.2 inch or berriers of up to 0.016 ever, when an air gap of 0.4 inch or a barrier of 0.036 inchthick brass was introduced into the system failures were inch-thick stainless steel. There was no failure of the detonator to initiate the PB-RDX pellet in these tests. Howproduced in several instances.

served when the detonator was in direct contact with the no failure of the detonator to initiate the pellet was obpellet. However, when an air gap of 0.2 inch was intro-Similar tests were conducted at -65 if. In these tests, duced between the detonator and pellet, failure was ob-

# with air gaps of up to 0.2 inch or barriers of up to 0.010 inch-thick stainless steel. There was no failure e- the detonator to initiate the PB-RDX pellet in these tess. However, when an air gap of 0.4 inch or a barner of (+0)36 inch-thick brass was introduced into the system fair res were produced in several instances.

served when the detonator was in direct contact with the Similar tests were conducted at -65 F. In t.ese tests, no failure of the detonator to initiate the pelle; was obas introduced between the detonator and pellet, failure was obpellet. However, when an air gap of 0.2 inch served.

! when do detonator was in direct contact with the However, when an air gap of 0.2 inch was intro-

faced between the detonator and pollet, failure was ob-

111111

to fabure of the defouator to initiate the pellet was ob-

Studies firsts were conducted at -657F

proceed in several instances,

In these tests,

UNCLASSIFIED UNITERMS Shainheit, 1..

Wagner, R. L.

UNCLASSIFIED

UNCLASSIFIED

UNITERMS Shainbeit, 1..

Wagner, R. L.

UNCLASSIFIED

lests were conducted at ambient temperature with the M46 tables. Unclassified report from the Artillery Amenunition DETERMINATION OF THE FEASIBILITY OF INITIA-The M46 Stab Defonator was used to autiate PB-RDA pel-Detonator in direct contact with the PB-RDX pellet and ING PRIRDY PULLETS USING THE M46 STAB DET-: - burel Report 3110, September 1963, 28 pp. Figures L. Joratory, Ammunition Engineering Directorate. Pratinny Arsenal, Dover, New Jersey has maker varied test conditions. 1. ondard Shambort R. hora ! Wagner Robert 1 Wagner Accession No. Accession No. CNATOR ONATOR Hi PR RDA redbes IV ATE, s. b detector 1 Usphysics Materials 2 Fitting Detonators Wagner Refert !.. IR. PB-RDN pellets IV. M46 seb detonator I shirdent Lemal 2. Electric Detenators 1. Explosives Materials H. Wagner, Robert L. I. Shainbeit, Lounard CHURCHASSIETED UNCLASSIFIED UNCLASSIFIED . . . . . . . . . . . SINT CLIVE - - Tuttation CNITERIAS - - Initiation Defountion Explosive 1) tendor 11.16.111.11 Laplacian 111:11:11:111 \* 1.0 | 1.0 E Scale Services of the Control of the Service of the Mass Mass Control of the Cont 7146 in the control of the data to the properties of the M46 period of the PR RDX proflet and THE CHAIN ALTON OF THE LEASINGTON OF WHITE THE ACTION OF STAB DETAILS A PARTY OF STAB DETAILS AND ACTION OF STAB DETAILS. Color of the September 1965, 18 pp. Biggins of the Lord for the Color for Artibor, Americalism expects to the Artibor, Americalism to the colors of the properties. A transfer of the control of the con ALL VON THE RESERVE TO THE SERVE OF THE SERV THE RIVE THEIR USING THE MAS STAB DET-THE FEMILY WILLY OF THE FEASIBILITY OF INITIA-149 NOT 10 THE TANK OF THE PROPERTY OF THE PARTY IN THE (10.00) AD .... (1) A MAN TO MAN TO MAN TO THE TOTAL OF THE TOTA Service Americal Donor New Jersey The state of the state of and the state of THE STATE OF THE STATE OF 17 1011 .... HOPE . .

# 4.0

.

DETERMINATION OF THE FEASIBILITY OF INITIA-ING PB-RDX PELLETS USING THE M46 STAB DET. Picatinny Arsenal, Dover, New Jersey

Leondard Shambert

tables. Unlassified report from the Artiflery Amunualion Trobingol Separe 3110, September 1963, 28 pp. figures, Laboratory, Aremunition Engireering Directorate.

Ple Maß Stab Defender was used to initiate PB-RDX pellets under varied test conditions. lests were conducted at ambient temperature with the M46 Detonator in direct contact with the PB KDX pellet and

I. Explosives Materials 2 Electric Determines - - Initiation

UNCLASSIFIED

I. Shambelt 1 eeu d' II. Magnet, Kest err 1 IV. M46 stab Jetser. III. FB RDN pellet

は公田田とい

Determiner Explosis initiation Pellets 2::5 CELETAL CARTEEN

# CHILLSSEED

AD \_\_\_\_\_

1. Explorises Notes 8 - - Indiales.

Then bear a

Shirt it. H Wagner, holes भारत है। अन्तर वास्त्र कार्या

W MESTS 

a Manda Car Inthitia n Pellets

Detonat 17. ニニニンシーンとし

(OVET)

UNCLASSIFIED

(OVET)

UNCLASSIFIED UNITERMS Shainheit, 1 Wagner, R. L	UNCLASSIFIED	UNCLASSIFIED UNITERMS Shainbeit, L. Wagner, R. L.	UNCLASSIFIED
with air gaps of up to 0.2 inch or barriers of up to 0.010 inch-thick stainless steel. There was no failure of the detonator to initiate the PB-RDN pellet in these tests. However, when an air gap of 0.4 inch or a barrier of 0.036 inch-thick brass was introduced into the system failures, were produced in several instances.  Similar tests were conducted at -65 F. In these tests, no failure of the detonator to initiate the pellet was observed when the detonator was in direct contact with the pellet. However, when an air gap of 0.2 inch was introduced between the detonator and pellet, failure was observed.		with air gaps of up to 0.2 inch or barriers of up to 0.010 inch-thick stainless steel. There was no failure of the detonator to initiate the PB-RDX pellet in these tess. However, when an air gap of 0.4 inch or a barrier of 0.036 inch-thick brass was introduced into the system fair res were produced in several instances.  Similar tests were conducted at $-65  \mathrm{F}$ . In these tests, no failure of the detonator to initiate the pellet was observed when the detonator was in direct contact with the pellet. However, when an air gap of 0.2 inch has introduced between the detonator and pellet, failur was observed.	FIED
UNCLASSIFIED UNITERMS Shainheit L. Wagner, R. L.	UNCLASSIFIED	UNCLASSIFIED UNITERMS Shainheit, L. Wagner, R. L.	UNCLASSIFIED
with air gaps of up to 0.2 inch or barriers of up to 0.010 in h thick standers steed. There was no failure of the detected of the barrier to initiate the PB-RDX pediet in these tests. However, when an air gap of 0.4 inch or a barrier of 0.036 inchilured bars was introduced into the system failures were produced in several instances.  Similar tests were conducted at -65°F. In these tests, no fadure of the detonator to initiate the pediet was observed when the detonator was in direct contact with the pediet. However, when an air gap of 0.2 inch was introduced between the detonator and pediet, failure was observed.		with or gaps of up to 0.2 inch or barriers of up to 0.010 constitutes stod. There was no failure of the detector when an arranged of timeh or a barrier of 0.036 inches to a barrier of 0.036 inches a constitution of the detailers.  So that a set a pere conducted at -657F. In these tests, and in the pellet was observed about the detailator to initiate the pellet was observed between the detailator and pellet, failure was observed.	

## TABLE OF DISTRIBUTION

		Copy Number
1.	Commanding General	
	U. S. Army Munitions Command	
	Dover, New Jersey	
	ATTN: AMSMU-A	1
2.	Commanding Officer	
	Picatinny Arsenal	
	Dover, New Jersey	
	ATTN: SMUPA-VA6	2-6
	SMUPA-DX1	7-8
	SMUPA-DR4	9-18
	SMUPA-DR6	19-20
	SMUPA-DE2	21-22
	SMUPA-DR5	23-24
	SMUPA-DS1	25-26
	SMUPA-NR2	27-28
	SMUPA-DW7	29-30
3.	Defense Documentation Center	
	Cameron Station	
	Alexandria, Virginia	31-50
4.	Commander	
	Naval Ordnance Laboratory	
	White Oak, Silver Spring	
	Maryland	
	ATTN: Library	51
	V. J. Menichelli, 3-115	52
	Howard Leopold, 30-118	53
5.	Commanding Officer	
	Harry Diamond Laboratories	
	Washington 25, D. C.	
	ATTN: Technical Reference Section	54-55
	Milton Lipnick	56
	Commanding Officer	
	U. S. Naval Ordnance Laboratory	
	Corona, California	
	ATTN: Library	57
	Wilson A. Flartey, code 551	58

## TABLE OF DISTRIBUTION (con'd)

		Copy Numb
7.	Commanding Officer Frankford Arsenal	
	Philadelphia 37, Pennsylvania	
	ATTN: Library	59-60
8.	Commander	
	Naval Ordnance Test Station	
	China Lake, California	
	ATTN: Library	61-62
	David A. Calpitts, code 4542	63
9.	Commanding Officer	
	Naval Ordnance Plant	
	Macon, Georgia	
	ATTN: Library	64-65
	Phillip F. Powell, PD208	66
10.	AFMTC	
	Patrick Air Force Base, Florida	
	MTORS-3	
	ATTN: Library	67-68
	Mr. Fewell	69
11.	DET 4 ASD	
	Eglin Air Force Base, Florida	
	ATTN: ASQWR Carl Kyselka	70
	Library	71-72